




Ultra Pro

SP2290 AND SP2295 PUMP SERIES REPLACEMENT PARTS

Parts for Pump Models: SP2290, SP2295, SP2290ET, SP2295ET



Part No.	Description	Ctn. Qty.
SPX1500D2A	Strainer Cover	1
SPX1500P	Strainer O-Ring	1
SPX1500LX	Basket	1
SPX1500CAP	Strainer Housing	1
SPX1700FG	Drain Plug (optional)	—
SPX1700FG	Drain Plug w/Gasket	1
SPX1500W	O-Ring	1
SPX1500N2	Bolt, No. 10-24 Hex. Head	8
SPX1580BP	Housing Cover	1
SPX1580Z1	Housing O-ring	1
SPX1500E	Impeller	1
SPX1500KA	Seal Assembly - (2005 SPX1250XZ2C)	1
SPX1580AAP	Pump Housing	1
SPX1500Y2	Nut, No. 10-24 Hex.	8
SPX1500Q2	Shaft Sleeve	1
SPX1509ZIUF	Motor	1
SPX2090B	Shroud	1
SPX2090A	Motor Housing	1
	Motor-To-Housing Bolt To order, specify manufacturer, HP and Model No.	4
SPX2601C	Elevated Mounting Base (optional)	—
SPX2090C	Motor End Cover (optional)	—
ECX1325R	Switch Assembly (optional)	—
ECX13252R	Switch Assembly - 2speed	—
SPX2090CET	Motor End Cover (electronic timer)	—